

1. existing extension



2. internal view



By [signature]

3. internal view- not well connected



by tran nguyen

4. extension increased to make it bigger



5. space became bigger- too big?



6. redistribution of space needed



7 new layout - still not working...



by tran nguyen

8. new layout - works better with partial subdivision.



**10. final design. dining table:
interchangeable location**



11. materials and lighting modelled



12. materials / furniture easily adjusted on model



**13. chosen theme put
through out.**



**14. Recessed lighting
sliding doors**

**open riser
stairs**

parquet floor

oak banisters

